403-521 Market Street (Houses and Commercial Buildings)
(Mill Hill Historic District)
517 Market Street (House)
Trenton
Mercer County
New Jersey

HABS No. NJ-901-Q

HABS NJ 11-TRET, 12-Q-

## **PHOTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey National Park Service Department of the Interior Washington, DC 20013-7127

Inited States Department of the Interior Ieritage Conservation and Recreation Service Vashington, DC. 20243

NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY HABS ARCHITECTURAL DATA FORM

ARCHITECTURAL DATA FORM

12-Q-

9/2/81

| STATE<br>New Jersey  | COUNTY   | TDWN OR VICINITY City of Trenton                                      |
|--|--|---|
|  | RUCTURE (INCLUDE SOURCE FOR NA                                     |   |
| 517 Market Street  | ,  | NJ-901-Q  |
| SECONDARY OR COMMON  | NAMES OF STRUCTURE   |   |
| COMPLETE ADDRESS (DI   | ESCRIBE LOCATION FOR RURAL SIT                                     | TE 9 )  |
| 517 Market Street  | JOHN DE LOURING TON NORME STE                                      |   |
| DATE OF CONSTRUCTION   | (INCLUDE SOURCE) ARCHITECT   | (S) (INCLUDE SOURCE)  |
| 1860-1874 (Market  |  | •   |
|  |  | DE ORIGINAL USE OF STRUCTURE)   |
| of residential stru  | uctures representative of verna                                    | storic District, a homogeneous group cular interpretations of popular |
|  | g the second hal of the ninetee                                    | enth century.   |
| STYLE (IF APPROPRIA) Vernacular  | (E)  |   |
| MATERIAL OF CONSTRUC   | TION (INCLUDE STRUCTURAL SYST                                      | EMS·)   |
| Brick and Masonry  |  |   |
|  | OF STRUCTURE (SKETCHED FLOOR                                       | R PLANS ON SEPARATE PAGES ARE ACCEPTABLE                              |
| Rectangular, 15' x   |  |   |
| EXTERIOR FEATURES OF   |  | and a transom over the entrance.                                      |
| July, Juliery Serv   | ictale weigh a bracketed cornice                                   | and a cransom over the entrance.                                      |
| ·  |  | ·   |
| INTERIOR FEATURES OF   | F NOTE (DESCRIBE FLOOR PLANS,                                      | IF NOT SKETCHED)  |
| Side hall plan   |  |   |
|  |  |   |
| MAJOR ALTERATIONS A  | ND ADDITIONS WITH DATES  |   |
| Two story rear add   | ition  |   |
| PRESENT CONDITION A  | ND USE   |   |
| Fair - unoccupied  |  |   |
| OTHER INFORMATION AS   | APPROPRIATE  |   |
|  |  |   |
| SOURCES OF INFORMAT  | ON (INCLUDE LISTING ON NATION                                      | NAL REGISTER STATE REGISTERS FTC )                                    |
| Historic/Architect   | ural Resources, Technical Suppo<br>ect, Prepared by Heritage STudi | NAL REGISTER, STATE REGISTERS, ETC.) ort Document les August 1979     |
| THE PROPERTY OF THE PROPERTY O | 200, richared by heritage Study                                    | . co, nuguou, 1979.   |
| COMPILER, AFFILIATIO   | N  | IDATE   |

Ruman of Environmental Analysis, N.J. Dent. of Transportation